

SERVICE BULLETINS & AIRWORTHINESS DIRECTIVES REPETITIVE

Helicopter Model: **EC120B**
 S/N: ████████
 Reg. ████████
 T.T. **1874:31:**
 Date: **27-mag-2015**
Engine s/n.: **34290**
T.T. ████████
1874:31:
Cycles NG: **2128,50**
Cycles NTL: **2512,60**
CY CELL.: **4031**

Service Bulletins Number	Intervall Inspection		Last Inspection		Next Inspection Heli T.T. or date		Residue		NOTE
	Hours	Months	Hours	Date	Hours	Date	Hours	Days	
SB MOTORE ARRIUS 2F									NOTE
Sostituzione privilege injection pipe (AD 2012-0150 - SB A319-73-4001 Rev L)	400:		1874:31:	2-apr-2015	2274:31:		400:00		
Injection half-mainfolds and privilege injector 319-73-4083A	400:		1874:31:	2-apr-2015	2274:31:		400:00		1 time?
Bossage sur carter turbine (SB 319-73-4003R2)	1000:		1525:39:	17-nov-2011	2525:39:		651:08		Recommended
Check Posizione corretta del filtro FCU (F-2005-088 - SB 319-72-4823)	500:	24	1682:38:	24-apr-2014	2182:38:	23-apr-2016	308:07	332	
Ispez gioco fra tubo aria P3 (1 sezione) e RH metà parete post	100:		1874:31:	2-apr-2015	1974:31:		100:00		
EASA AD 2011-0182 R1 (SB 319-75-4810)	500:		1525:39:	17-nov-2011	2025:39:		151:08		
SB 319-72-4822 - Centrifugal diffuser vane check									
SB CELLULA									NOTE
AD 2010-0026-E - ASB 05A012 - Check for crack in main rotor hub	15:		1874:31:	2-apr-2015	1889:31:	-	15:00	-	A cura pilota
AD 2007-0211 - SB 05A006 - Tail Rotor Drive Shaft	110:		1874:31:	2-apr-2015	1984:31:	-	110:00	-	
Controllo dei fori di drenaggio pianetto orizzontale (SB 05-004)	500:	24	1682:38:	24-apr-2014	2182:38:	23-apr-2016	308:07	332	
1 time inspection									

